

Welding CD-ROM

TC 9-237	WELDING THEORY AND APPLICATION 774pp 7 MAY 1993
TB 55-1900-204-24	ARC WELDING ON WATER BORNE VESSELS 7pp 10 APRIL 1974
TB 9-3439-203/1	CONVERSION OF WELDING ELECTRODE HOLDER FOR SUPPLEMENTAL AIR-ARC METAL CUTTING 8pp 18 MAY 1967
TB 9-4940-319-30	SHOP EQUIPMENT, WELDING SHOP (NSN 4940-00- 209-6240) INSTALLATION IN ONE 280 MAINTENANCE SHELTER AND ONE IS0-2-1 MAINTENANCE SHELTER 37pp 24 JAN 1968
TM 1-1500-204-23-8	AVIATION UNIT MAINTENANCE AND AVIATION INTERMEDIATE MAINTENANCE MANUAL FOR GENERAL AIRCRAFT MAINTENANCE VOL 8 55pp 31 JULY 1992
TM 5-3431-200-15	OPERATOR, ORGANIZATIONAL FIELD, AND DEPOT MAINTENANCE MANUAL WELDING SET, ARC, INERT GAS SHIELDED PLASTIC OR METAL LINED GUN FOR 3/64 IN. WIRE DC 115V WESTINGHOUSE MODEL SA-135 FSN 3431-879- 9709 73pp 08/62
TM 5-3431-200-20P	ORGANIZATIONAL MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LIST WELDING SET, ARC, INERT GAS SHIELDED PLASTIC OR METAL LINED GUN FOR 3/64 IN. WIRE DC 115V WESTINGHOUSE MODEL SA-135 FSN 3431-879- 9709 56pp 02/69
TM 5-3431-200-35P	DIRECT AND GENERAL SUPPORT AND DEPOT MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LIST WELDING SET, ARC, INERT GAS SHIELDED PLASTIC OR METAL LINED GUN FOR 3/64 IN. WIRE DC 115V WESTINGHOUSE MODEL SA-135 FSN 3431-879-9709 52pp 02/69
TM 5-3431-201-10	OPERATORS MANUAL WELDING MACHINE, ARC, GENERATOR, DIESEL DRIVEN SINGLE OPERATOR REMOTE CONTROL 300 AMP DC ARC SKID MTD 60 AMP 20V MIN 375 AMP AT 40 V MAX CURRENT 115 V 3 KW AUXILIARY POWER LIBBY MODEL ODW-300 FSN 3431-894-1573 58pp 08/62
TM 5-3431-203-15	OPERATOR, ORGANIZATIONAL, DIRECT AND GENERAL SUPPORT AND DEPOT MAINTENANCE MANUAL WELDING MACHINE ARC INERT

	SHIELDED TRANSFORMER 300 AMP 10 TO 400 AMP AC STRAIGHT POLARITY 10 TO 00 AMP DC REVERSE POLARITY MIDSTATES MODEL MAG 00 AC/DC T 14 FSN 3431-862-6670 116pp 02/67
TM 5-3431-204-20P	ORGANIZATIONAL MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LIST WELDING MACHINE, ARC GENERATOR GASOLINE ENGINE DRIVEN SINGLE OPERATOR REMOTE CONTROL 300 AMP DC ARC SKID MTF 60 AMP AT 20 V MIN 375 AMP AT 40 V MAX CURRENT DC 115 V 3 KW AUXILIARY POWER MIL SPEC W-13768 HOBART MODELS GH-3152 FSN 3431-351-9209 AND MODEL GH-3153-S FSN 3431-239-8186 68pp 01/63
TM 5-3431-204-35P	FIELD AND DEPOT MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LISTS WELDING MACHINE, ARC GENERATOR GASOLINE ENGINE DRIVEN SINGLE OPERATOR REMOTE CONTROL 300 AMP DC ARC SKID MTF 60 AMP AT 20 V MIN 375 AMP AT 40 V MAX CURRENT DC 115 V 3 KW AUXILIARY POWER MIL SPEC W-13768 HOBART MODELS GH-3152 FSN 3431-351-9209 AND MODEL GH-3153-S FSN 3431-239-8186 112pp 01/63
TM 5-3431-205-15	OPERATOR, ORGANIZATIONAL DIRECT SUPPORT AND DEPOT MAINTENANCE MANUAL WELDING MACHINE ARC GENERATOR GASOLINE ENGINE DRIVEN 300 AMP DC LIBBY MODELS LE-300, LEW-300, LEB-300, FSN 3431-810-9696, 3431-991-2961, 3431-072-0327, 159pp 07/1968
TM 5-3431-205-20P	ORGANIZATIONAL MAINTENANCE MANUAL REPAIR PARTS AND SPECIAL TOOLS LISTS WELDING MACHINE ARC GENERATOR GASOLINE ENGINE DRIVEN 300 AMP DC LIBBY MODELS LE-300, LEW-300, LEB-300, FSN 3431-810-9696, 3431-991-2961, 3431-072-0327, 159pp 07/1968
TM 5-3431-205-35P	DIRECT AND GENERAL SUPPORT AND DEPOT MAINTENANCE MANUAL REPAIR PARTS AND SPECIAL TOOLS LISTS WELDING MACHINE ARC GENERATOR GASOLINE ENGINE DRIVEN 300 AMP DC LIBBY MODELS LE-300, LEW-300, LEB-300, FSN 3431-810-9696, 3431-991-2961, 3431-072-0327, 144pp 01/1971
TM 5-3431-207-15	OPERATOR, ORGANIZATIONAL, FIELD AND DEPOT MAINTENANCE MANUAL WELDING MACHINE ARC GENERATOR ELECTRIC MOTOR DRIVEN AC 220V 3-PHASE 60 CYCLE SINGLE OPERATOR REMOTE CONTROL 300 AMP DC ARC

	WHEEL MTD 4 WHEEL STEEL TIRES 60 AMP AT 20V MIN 375 AMP AT 40V MAX CURRENT LIBBY MODEL LA-300 FSN 3431-081-8059 57pp 09/1963
TM 5-3431-207-20P	ORGANIZATIONAL MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LISTS WELDING MACHINE ARC GENERATOR ELECTRIC MOTOR DRIVEN AC 220V 3-PHASE 60 CYCLE SINGLE OPERATOR REMOTE CONTROL 300 AMP DC ARC WHEEL MTD 4 WHEEL STEEL TIRES 60 AMP AT 20V MIN 375 AMP AT 40V MAX CURRENT LIBBY MODEL LA-300 FSN 3431-081-8059 43pp 12/1968
TM 5-3431-207-35P	DIRECT AND GENERAL SUPPORT AND DEPOT MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LIST MANUAL WELDING MACHINE ARC GENERATOR ELECTRIC MOTOR DRIVEN AC 220V 3-PHASE 60 CYCLE SINGLE OPERATOR REMOTE CONTROL 300 AMP DC ARC WHEEL MTD 4 WHEEL STEEL TIRES 60 AMP AT 20V MIN 375 AMP AT 40V MAX CURRENT LIBBY MODEL LA-300 FSN 3431-081-8059 55pp 12/1968
TM 5-3431-208-20P	ORGANIZATIONAL MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LISTS WELDING SET ARC INERT GAS SHIELDED PLASTIC OR METAL LINED GUN FOR 3/64 IN. WIRE DC 115V LINDE MODEL SWM-9-A FSN 3431-972-7672 48pp 05/1970
TM 5-3431-208-35P	DIRECT AND GENERAL SUPPORT AND DEPOT MAINTENANCE MANUAL REPAIR PARTS AND SPECIAL TOOLS LIST WELDING SET ARC INERT GAS SHIELDED PLASTIC OR METAL LINED GUN FOR 3/64 IN. WIRE DC 115V LINDE MODEL SWM-9-A FSN 3431-972-7672 48pp 05/1970
TM 5-3431-213-14	OPERATOR, ORGANIZATIONAL, DIRECT SUPPORT, AND GENERAL SUPPORT MAINTENANCE MANUAL INCLUDING REPAIR PARTS AND SPECIAL TOOLS LIST WELDING MACHINE ARC GENERAL AND INERT GAS SHIELDED TRANSFORMER-RECTIFIER TYPE AC AND DC 300 AMP RATING AT 60% DUTY CYCLE HARNISCHFEGER MODELS DAR-300HFSG AND 2100H2007 FSNS 3431-984-3401 AND 3431-926-3746 180pp 12/1969
TM 5-3431-217-15	ORGANIZATIONAL DS GS AND DEPOT MAINTENANCE MANUAL INCLUDING REPAIR PARTS WELDING MACHINE ARC GENERATOR ELECTRIC DRIVEN MOTOR 300 APM DC ARC 220/440V 60 CYCLE 3 PHASE WHEEL MOUNTED

	HARNISCHFEGER MODEL W300 MG FSN 3431-226-1659 101pp APRIL 1965
TM 5-3431-224-15	ORGANIZATIONAL DIRECT SUPPORT GENERAL SUPPORT AND DEPOT MAINTENANCE MANUAL FOR WELDING MACHINE ARC CC XFMR/RECT TYPE 200 AMP SINGLE OPERATOR MILLER MODEL SRH-222 FSN 3431-926-3852 22pp 15 NOV 1968
TM 5-3431-225-15	OPERATOR ORGANIZATIONAL DIRECT AND GENERAL SUPPORT AND DEPOT MAINTENANCE MANUAL WELDING MACHINE ARC GENERAL AND INERT GAS SHIELDED TRANSFORMER 300 AMP 5 TO 460 AMP AC 5 TO 350 AMP DC MILLER MODEL 330A/B/SP FSN 3431-620-0858 87pp 03/1969
TM 5-3431-226-15	OPERATORS ORGANIZATIONAL DIRECT SUPPORT GENERAL SUPPORT AND DEPOT MAINTENANCE WELDING SET ARC INERT GAS SHIELDED WATER COOLED ALUMINUM WELDING GENERAL PURPOSE AIRCO MODEL 2351 1209 FSN 3431-731-4163 93pp 25 JUNE 1969
TM 5-3431-226-23P	ORGANIZATIONAL AND DIRECT SUPPORT MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LIST WELDING SET ARC INERT GAS SHIELDED WATER COOLED ALUMINUM WELDING GENERAL PURPOSE AIRCO MODEL 2351 1209 FSN 3431-731-4163 82pp 3 DEC 1970
TM 5-3431-227-14	OPERATORS ORGANIZATIONAL DS AND GS MAINTENANCE MANUAL WELDING SET ARC INERT GAS SHIELDED AIR COOLED METAL LINED GUN FOR 3/64 IN. WIRE WESTINGHOUSE MODEL SA-136 FSN 3431-121-5878 38pp 6 AUG 1969
TM 5-3431-227-24P	ORGANIZATIONAL DS AND GS AND DEPOT MAINTENANCE MANUAL REPAIR PARTS AND SPECIAL TOOLS LISTS WELDING SET ARC INERT GAS SHIELDED AIR COOLED METAL LINED GUN FOR 3/64 IN. WIRE WESTINGHOUSE MODEL SA-136 FSN 3431-121-5878 40pp 7 JULY 1971
TM 5-3431-228-14	OPERATOR ORGANIZATIONAL DIRECT SUPPORT AND GENERAL SUPPORT MAINTENANCE MANUAL WELDING MACHINE ARC AC/DC 300 AMP TRANSFORMER RECTIFIER CONSTANT CURRENT BASE MOUNTED EUTECTIC CORP MODEL MD301 FED FSN 3431-235-4728 96pp 30 DEC 1970
TM 5-3431-228-20P	ORGANIZATIONAL MAINTENANCE REPAIR PARTS AND SPECIAL TOOL LISTS WELDING

	MACHINE ARC AC/DC 300 AMP TRANSFORMER RECTIFIER CONSTANT CURRENT BASE MOUNTED EUTECTIC CORP MODEL MD301 FED FSN 3431-235-4728 31pp 27 OCTOBER 1971
TM 5-3431-228-34P	DIRECT SUPPORT GENERAL SUPPORT AND DEPOT MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LISTS WELDING MACHINE ARC AC/DC 300 AMP TRANSFORMER RECTIFIER CONSTANT CURRENT BASE MOUNTED EUTECTIC CORP MODEL MD301 FED FSN 3431-235-4728 46pp 28 OCTOBER 1971
TM 5-3431-229-13	OPERATOR ORGANIZATIONAL AND DIRECT SUPPORT MAINTENANCE MANUAL INCLUDING REPAIR PARTS AND SPECIAL TOOLS LISTS WELDING SHOP TRAILER MOUNRED LIBBY MODEL UNASSIGNED FSN 3431-935-7821 73pp 10 FEBRUARY 1972
LO 5-6115-586-12	LUBE ORDER POWER PLANT UTILITY GAS TURBINE ENGINE DRIVEN LIBBY WELDING CO MODEL LPU-71 7pp 18 NOVEMBER 1972
TM 5-6115-590-12	OPERATOR AND ORGANIZATIONAL MAINTENANCE MANUAL POWER PLANT UTILITY (MUST) GAS TURBINE ENGINE DRIVEN AMERTECH CORP MODEL APP-1 243pp 03/1977
TM 5-6115-586-34	DIRECT SUPPORT AND GENERAL SUPPORT MAINTENANCE MANUAL POWER PLANT UTILITY GAS TURBINE ENGINE DRIVEN LIBBY WELDING CO MODEL LPU-71 FSN 6115-165-3842 255pp JUNE 1972
TM 5-6115-586-34P	DIRECT SUPPORT AND GENERAL SUPPORT MAINTENANCE MANUAL REPAIR PARTS AND SPECIAL TOOLS LISTS POWER PLANT UTILITY GAS TURBINE ENGINE DRIVEN LIBBY WELDING CO MODEL LPU-71 FSN 6115-165-3842 522pp 08/72
TM 5-6115-590-20P	ORGANIZATIONAL MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LISTS POWER PLANT UTILITY (MUST) GAS TURBINE ENGINE AMERTECH CORP MODEL APP1 NSN 6115-00-937-0929 375pp 10 SEPTEMBER 1979
TM 5-6115-590-34P	DIRECT SUPPORT AND GENERAL SUPPORT MAINTENANCE REPAIR PARTS AND SPECIAL TOOLS LISTS POWER PLANT UTILITY (MUST) GAS TURBINE ENGINE AMERTECH CORP MODEL APP1 NSN 6115-00-937-0929 612pp 7 SEPTEMBER 1979
TM 9-3431-254-14&P	OPERATOR ORGANIZATIONAL DIRECT SUPPORT

	AND GENERAL SUPPORT MAINTENANCE MANUAL INCLUDING REPAIR PARTS LIST FOR WELDING MACHINE MODEL GCC-300W FSN 3431-01-032-6289 141pp 08/84
TM 9-3431-258-14&P	OPERATORS ORGANIZATIONAL DIRECT SUPPORT AND GENERAL SUPPORT MAINTENANCE MANUAL INCLUDING REPAIR PARTS LIST FOR TORCH OUTFIT WELDING GAS MODEL 137 NSN 3431-00-691-1415 47pp 31 JULY 1981
TM 9-3431-260-14&P	OPERATORS ORGANIZATIONAL DIRECT SUPPORT AND GENERAL SUPPORT MAINTENANCE INCLUDING REPAIR PARTS LIST FOR WELDING MACHINE ARC MODEL SAE-400 LICOLN ELECTRIC CO NSN 3431-00-498-6258 23pp JULY 1981
TM 55-4920-214-15	OPERATOR ORGANIZATIONAL FIELD AND DEPOT MAINTENANCE MANUAL SHOP SET AIRCRAFT MAINTENANCE SEMITRAILER MOUNTED SET C5 WELDING 93pp OCTOBER 1961
TM 55-4920-404-30&P	AVIATION INTERMEDIATE MAINTENANCE INCLUDING REPAIR PARTS FOR SHOP SET COMPLEX AVIM AIRMOBILE 175pp 29 JUNE 1978